

**Date Complaint Filed:** 08/07/2013

**Component(s):** POWER TRAIN

**Date of Incident:** 08/04/2013

**NHTSA ID Number:** 10533996

**All Products Associated with this Complaint** ▼

**Details** ▲

**1 Associated Document** 

**Crash:** No    **Fire:** No    **Number of Injuries:** 0    **Number of Deaths:** 0

**Manufacturer:** Chrysler Group LLC

**Vehicle Identification No. (VIN):** 3D7ML48C76G...

**SUMMARY:**

TL\* THE CONTACT OWNS 2006 DODGE RAM 3500. THE CONTACT STATED THE IGNITION KEY WAS TURNED WITHOUT THE CLUTCH ENGAGED AND THE VEHICLE BEGAN TO ROLL ON ITS OWN DUE TO THE FAULTY CLUTCH SAFETY SWITCH. THE FAILURE RECURRED ON SEPARATE OCCASIONS. THE VEHICLE WAS TAKEN TO AN AUTHORIZED DEALER. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS NOTIFIED OF THE PROBLEM. THE APPROXIMATE FAILURE MILEAGE WAS 130,000. UPDATED 09-26-13 \*BF

**Request Research** 