



**Das Auto.**

Volkswagen of America, Inc.  
3800 Hamlin Road  
Auburn Hills, MI 48326

April 2015

This notice applies to your vehicle:

**Subject: Emissions Service Action 2306 – ECM Software  
Certain 2010-2014 Model Year Volkswagen Vehicles Equipped with a 2.0L TDI®  
Clean Diesel Engine**

Dear Volkswagen Owner,

As part of Volkswagen's ongoing commitment to our environment, and in cooperation with the United States Environmental Protection Agency and the California Air Resources Board, we are informing you of our decision to conduct an emissions service action on certain 2010-2014 model year Volkswagen vehicles equipped with a 2.0L TDI® Clean Diesel engine. Our records show that you are the owner of a vehicle affected by this action.

**What is the issue, and what will we do?**

The vehicle's engine management software has been improved to assure your vehicle's tailpipe emissions are optimized and operating efficiently. Under certain operating conditions, the earlier strategy may have increased the chance of the vehicle's MIL light illuminating. If the MIL illuminates for any reason, your vehicle will not pass an IM emissions inspection in some regions.

To address this issue, your authorized Volkswagen dealer will update the ECM software in your vehicle. This work will take about one hour to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.

**IMPORTANT!**

**Please note that if the ECM in your vehicle has been "chipped," "tuned," or otherwise modified from original factory specifications with aftermarket components and/or software, work needed to repair, replace, or return the ECM to original factory specifications is NOT covered under this action.**

**What should you do?**

In order to limit any possible inconvenience, please contact your authorized Volkswagen dealer as soon as possible to schedule this service.